CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18. Sections 763 and 794, or the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorised person is prohibited by law. The reproduction of this form is prohibited.

			SECUI	RITY INFORMATION			
COUNTR	Y	USSR (Lening	rad Oblast)		REPORT		
SUBJECT		Leningrad Ha	rbor		DATE DISTR.	19 March	1953
					NO. OF PAGES	2	
DATE O	F INFO.		·		REQUIREMENT NO.	RD	
PLACE A	ACQUIRED				REFERENCES		;
	This	is UNEVALUA	ATED Informa	tion		•	
		тне	THE APPRAISAL	ONS IN THIS REPORT L OF CONTENT IS TEN PR KEY SEE REVERSE)			
1.	observed command and two	flags. Each stacks. The	ff the Baltiy n cruiser had deck line ra	skiy Zavod. The two triple to an straight from	: 12,000 tons disp ne vessels were ma arrets on the fore om the bow to the oth of the ship.	nned and flew and aft decks,	d.
					Severa	l days later on	
L				king test-runs y Zavod at that	off Kronshtadt. time.	The second crui	ser
2.	Baltiys		Both vessels		at the fitting-ou		in
	battery		The second secon	_		sels which were	
3.	The way			d were concealed part of the shi	ed by merchant ves lpyard.		•
-	The way moored: At the of the	for repairs : Marti Shipya vessel was f:	in the west p rd a similar inished, but	part of the shi cruiser was of the stacks had		th ways. The h	
-	The way moored: At the of the identif	for repairs : Marti Shipyan vessel was f: ied vessel wa r four old me	in the west produced a similar inished, but as under concernant vess	cruiser was of the stacks had struction on a els of between	ipyard. oserved at the sou I not been raised.	th ways. The h Another un- cruiser.	ull.
4.	The way moored: At the of the identif Three ogoing r	for repairs : Marti Shipyan vessel was f: ied vessel wa r four old me	in the west produced a similar inished, but as under concernant vess	cruiser was of the stacks had struction on a els of between	lpyard. Deserved at the soul not been raised. Way north of this 5,000 and 6,000 t	th ways. The h Another un- cruiser.	ull.
4.	The way moored : At the of the identif Three o going r forms.	for repairs : Marti Shipyar vessel was f: ied vessel wa r four old me epairs at the	in the west ; rd a similar inished, but as under con erchant vess e **Lanonerski; in the Zhda	cruiser was of the stacks had struction on a els of between y Shipyard. Th	lpyard. Deserved at the soul not been raised. Way north of this 5,000 and 6,000 t	th ways. The h Another un- cruiser. cons were under- iaircraft plat-	ull.

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)

	25 X 1
SECRET/CONTROL - U.S. OFFICIALS ONLY	
-2-	•
Guns were mounted in double mounts on the fore and aft decks. the guns were 12 or 13 cm in size. The destroyers had two quadruple torpedo	25X1
tubes The two destroyers had two stacks, were painted grey, Two additional destroyers of the same type were being reconditioned or rebuilt in the Zhdamov Shipyard. Eight auxiliary vessels were tied up in the yard.	25X1

Approved For Release 2009/09/11 : CIA-RDP80-00810A000200240002-1

SECRET/CONTROL - U.S. OFFICIALS ONLY